



Brandon Delaney

2/11/2019 E BHMTS04D 100-05446474

Interior Termite Inspection	X
Exterior Termite Inspection	X
Treatment	

INSPECTION FINDINGS

No Visible Termite Activity in/on Home	X
Active Termites in/on Home	
Inactive/Previous Termite History in/on Home	
No Termite Activity in Sentricon Stations	
Active/Previous Termites in Sentricon Stations	X

TREATMENT RECORD

Product Used	RHD
Amount / %	20 / 05
Stations Re baited/Replaced	0 / 0

CONSTRUCTION TYPE:

Craw Space Block Porch/Stoop

Basement Poured Concrete Open

Slab Pier/Brick Inaccessible

Other None

CONDITIONS CONDUCIVE TO TERMITES:

Earth to Wood Contact	EW	
Moisture	M	
Water Leak	WL	
Standing Water	SW	
Inaccessible Area	IA	
Area Treated	X	

KEY SYMBOLS:

Subterranean Termites Active	STA
Subterranean Termites Previous	STP

FOLLOW UP BY CUSTOMER

Please Call for Interior Inspection

Phone# 205-985-7009


2/11/19 X *Brandon Delaney*
Date Customer Signature

Termite Inspection

1.866.WAYNEST | CALLWAYNES.COM
2183 PARKWAY LAKE DR.
BIRMINGHAM, AL 35244

100-0982926
Shelia & Ira Chaffin
1309 19th Street South
Birmingham, AL 35205
Sentricon AA Station Inspection

Sentricon(205) 918-9090,inear Footage: _____



_____ Today Waynes recommended a termite treatment be performed.
I have chosen to opt out from recommended treatment. _____ (Customer Initials)

COMMENTS

Brandon Delaney
Waynes Termite Professional



Termite Inspection

100-0982926
Shelia & Ira Chaffin
1309 19th Street, South
Birmingham, AL 35205
Sentricon AA Station Inspection

1.866.WAYNES1 | CALLWAYNES.COM

2183 PARKWAY LAKE DR.
BIRMINGHAM, AL 35244

Ryan Lambert

2/15/2018 PC TS 04 100-04660841

Sentricon (205) 918-9090 Linear Footage: _____

Interior Termite Inspection	✓
Exterior Termite Inspection	✓
Treatment	

INSPECTION FINDINGS	
No Visible Termite Activity in/on Home	✓
Active Termites in/on Home	
Inactive/Previous Termite History in/on Home	
No Termite Activity in Sentricon Stations	✓
Active/Previous Termites in Sentricon Stations	

TREATMENT RECORD	
Product Used	2 HD
Amount / %	15 / 0.5
Stations Rebaited/Replaced	0

CONSTRUCTION TYPE:	
<input type="checkbox"/> Crawl Space	<input checked="" type="checkbox"/> Block
<input checked="" type="checkbox"/> Basement	<input type="checkbox"/> Poured Concrete
<input type="checkbox"/> Slab	<input type="checkbox"/> Pier/Brick
<input type="checkbox"/> Other	


PORCH/STOOP:	
<input type="checkbox"/> Open	
<input type="checkbox"/> Inaccessible	
<input type="checkbox"/> None	

CONDITIONS CONDUCIVE TO TERMITES:

Earth to Wood Contact	EW	
Moisture	M	
Water Leak	WL	
Standing Water	SW	
Inaccessible Area	IA	Customer Initials
Area Treated	X	X _____

KEY SYMBOLS:

Subterranean Termites Active	STA
Subterranean Termites Previous	STP



_____ Today Waynes recommended a termite treatment be performed.

I have chosen to opt out from recommended treatment. _____ (Customer Initials)

FOLLOW UP BY CUSTOMER COMMENTS

Please Call for Interior Inspection	No visible termite activity found!
Phone# 985-7009	

Thank You!

2/15/18 Customer Signature Ryan Lambert
Waynes Termite Professional